
1/7

FIG. 1



2/7

FIG. 2A

$W_k^{N}$	N=4	N=8	N=16	N=32	N=64	N=128	
			0	•	0	0	
						64	
				0		32	
					32	96	
					16	16	
				16	16	80	
				16	48	48	
		_				112	
		0			8	8	
					0	72	
		į		8	40	40	
					40	104	
			8		24	24	
		4			24	24	88
				24	56	88 56 120	
1.	0				56	120	
k	0		4 20	4	4		
					,	4	68
				4	1 36 -	36	
Ė						100	
					20	20	
				20	52	84	
				20		52	
						116	
]			12		12	12	
				12		76	
				12		44	
					44	108	
1	!				28	28	
				20		92	
				28	60	60	
						124	

FIG. 2B 3/7

$W_k^{N}$	N=4	N=8	N=16	N=32	N=64	N=128
			1	4	1	1
						65
				1	77	33
					33	97
					17	17
				17		81
				''	40	49
		1			49	113
		'			9	9
				9	9	73
				9	41	41
			9		41	105
			9		25	25
				25	25	89
				23	57	57
k	1				37	121
K					5	5
			5	5	5 37 -	69
						37
					37	101
					21	21
				21		85
		5		'	53	53
				_	33	117
					13 45	13
			13 29	13		77
		1				45
						109
					29 61	29
				29		93
				23		61
						125

FIG. 2C 4/7

$W_k^{\ N}$	N=4	N=8	N=16	N=32	N=64	N=128
			2			2
				_	2	66
				2	7.4	34
					34	98
					18	18
				10		82
				18	E 0	50
					50	114
		2			10	10
				40	10	74
			1.0	10	4.5	42
					42	106
			10		20	26
	2			0.0	26	90
				26	F0	58
1					58	122
k			6		c	6
				6	38	70
				0		38
						102
					22	22
				22		86
	1			22	5.4	54
		,			54	118
		6	14		14	14
				14		78
				14		46
						110
					30 62	30
				70		94
				30		62
						126

FIG. 2D 5/7

$W_k^{\ N}$	N=4	N=8	N=16	N=32	N=64	N=128
			3		3	3
				7		67
				3	75	35
					35	99
					19	19
				10		83
				19	E 4	51
		_			51	115
		3			44	11
				,,	11	75
				11	47	43
			44		43	107
			11		27	27
	3			27	27	91
				21	50	59
1.					59	123
k			7		7	59 123 7 71
				7		71
				'	39	39
i						103
			7		23 55	23
		7		27		87
				23		55
						119
			15		15	15
				15	13	79
				13	47	47
					4/	111
					31 63	31
				31		95
				31		63
						127

6/7



